

ANACONDA Copper Company

New Mexico Operations
P.O. Box 638
Grants, New Mexico 87020
505/876-2211



November 5, 1979

Mr. A. F. Czarnowsky
Area Mining Supervisor
United States Geological Survey
P. O. Box 26124
Albuquerque, New Mexico
87125

Dear Mr. Czarnowsky:

The following information is being submitted in accordance with the Jackpile-Paguate Minesite Reclamation Sampling Program. As per Mr. Nelson's requests, this information is being submitted as we have received it.

1. Radiological and Chemical analysis of reclamation site soils and vegetation.
2. Surface gamma emission from reclaimed sites.
3. Radon exhalation values from reclaimed sites.

Sincerely,

Meade A Stirland
Manager
Environmental Health and Safety

MAS/bg

Encls.

